



SERVICE BULLETIN

No.

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

NUMBER 124


August 30, 1954

SUBJECT: PA-22 Landing Gear

MODELS AFFECTED: All Model PA-22 Airplanes

A number of field service reports have been received to the effect that cracks have been appearing in the leading edge of the streamlined tube of the PA-22 landing gears at a point where it joins the inboard end of the axle.

Indications are that this is a fatigue failure and it is requested that all Model PA-22 airplanes listed above be modified by installing a reinforcing strap, part number 14415-00, as per the sketch below.



The reinforcement strap can be obtained from the Service Department of the Piper Aircraft Corporation, free of charge.

End